

SUBJECT: GEM0955/MF1255 COMPRESSOR

Number: 12-03
Product: Pearl/MFI
Date Issued: March 2012
From: Technical Service

Due to manufacturing considerations, the compressor for the GEM0955/MF1255 series has been changed. For GEM0955/MF1255 Versions 1 and 2 the original compressor is no longer available. The replacement kit includes: a new compressor, starting components, liquid line drier, compressor wiring harness, refrigeration tubing and adapters. This kit enables Versions 1 and 2 to use the new compressor.

<u>Model Number</u>	<u>Prior to Serial Number</u>	<u>Part Number</u>	<u>Description</u>
GEM0955 Air1&2, Water1&2	12021280012561	1051188-01	Replacement Kit
MF1255 Air1&2, Water1&2	12021280010734	1051188-01	Replacement Kit

GEM0955/MF1255 Version 3 will require the compressor only kit. (compressor, starting components and drier)

<u>Model Number</u>	<u>From Serial Number</u>	<u>Part Number</u>	<u>Description</u>
GEM0955 Air3, Water3	12021280012562	9181147-11	Compressor only Kit
MF1255 Air3, Water3	12021280010735	9181147-11	Compressor only Kit

Caution: As with all compressor replacements, the system will require a cycle check and adjustment of product controls to allow the maximum capacity output for the customer.